

Type	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition
1	BRS 7	road and repair and machine and vehicle and (module modular) and 404/\$.ccls.	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 13:48		
2	BRS 98	road and repair and machine and vehicle and (module modular) and robotic	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 14:01		
3	BRS 12	road and repair and machine and vehicle and (module modular) and 404/\$.ccls.	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 13:56		
4	BRS 29	700/245.cccls. and road\$	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 13:56		
5	BRS 52	road and repair and machine and vehicle and (module modular) and robotic and slot	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 13:58		
6	BRS 2	road and repair and machine and vehicle and robotic and 404/\$.cccls. and (remov\$ fit\$ attach\$)	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/19 14:02		